

June 9, 1999

Financial Affairs
Richard H. Hinds, Chief Financial Officer

**SUBJECT: REPORT OF PURCHASES MADE WITHIN GUIDELINES OF BOARD RULE
6Gx13- 3C-1.10**

The following "Superintendent Authorized Requisitions" (SAR) have had purchase orders issued within the guidelines of Board Rule 6Gx13- 3C-1.10 – Purchase Approval, which states that emergency purchases made in accordance with Board Rule 6Gx13- 3C-1.16—Emergency Purchases, and approved by the Superintendent or his designee, will be reported to the Board as soon as possible.

Fund Source
0100-General

M/WBE Eligibility
None

(1)

<u>PO DATE</u>	<u>PO NO.</u>	<u>COST CENTER-EXPLANATION-VENDOR</u>	<u>AMOUNT</u>
05/21/99	K00650896	This emergency request was required to repair the air-conditioning chillers at Thomas Jefferson Middle School. Failure of the air-conditioning system was disruptive to the education process. MCQUAY INTERNATIONAL D/B/A MCQUAY SERVICE 3540 W. PROSPECT ROAD, SUITE 201 FORT LAUDERDALE, FL 33309	\$13,064.45

(2)

<u>PO DATE</u>	<u>PO NO.</u>	<u>COST CENTER-EXPLANATION-VENDOR</u>	<u>AMOUNT</u>
05/21/99	K00651128	This emergency request was required to repair three (3) York chillers at William Turner Technical Educational Center. One chiller was inoperable, and two were operating below capacity and in danger of failure at any time. YORK INTERNATIONAL CORPORATION 3300 CORPORATE AVENUE, SUITE 114 FORT LAUDERDALE, FL 33331	\$26,166

(3)

<u>PO DATE</u>	<u>PO NO.</u>	<u>COST CENTER-EXPLANATION-VENDOR</u>	<u>AMOUNT</u>
05/21/99	K00651129	This emergency request was required to repair two (2) chillers at Henry Reeves Elementary School. One chiller was off-line and inoperable, and the second chiller was operating below capacity. YORK INTERNATIONAL CORPORATION 3300 CORPORATE AVENUE, SUITE 114 FORT LAUDERDALE, FL 33331	\$16,823

RHH/lja