Office of Superintendent of Schools Board Meeting of July 13, 2005

June 29, 2005

Office of School Facilities
Rose Diamond, Chief Facilities Officer

SUBJECT:

FINAL CHANGE ORDER (CHANGE ORDER NO. 1) PROJECT NO. A0809C ROOF REPLACEMENT

BANYAN ELEMENTARY SCHOOL

3060 SW 85 AVENUE, MIAMI, FLORIDA

COMMITTEE: FACILITIES AND CONSTRUCTION REFORM

This request for change in the construction contract includes six items for the School Board's confirmation and consideration. Attachment A presents a description of the items, the cause for each change, the effect upon the contract, and the action recommended to the Board. In order to prevent delay in the completion of the project, staff authorized the Contractor to proceed with items 1 and 2. These items are presented to the Board for confirmation and consideration as required by State Statute.

Change Items Synopsis: These changes are primarily due to improvements to existing roof drainage and unforeseen existing conditions at this 48-year-old facility, and include a credit for FPL insulation rebate.

This change will <u>increase</u> the contract price by \$22,687 and <u>extend</u> the contract completion date by 188 days. These items have been recommended by the Project Architect and were confirmed/approved by the Technical Review Committee, subsequent to completion, on June 21, 2005. They were found to be necessary, fair, and equitable.

RECOMMENDED: That The School Board of Miami-Dade County, Florida, confirm

Final Change Order (Change Order No. 1) on Project No. A0809C, Roof Replacement, Banyan Elementary School for an additional cost of \$22,687 and approve a time extension of 188 days.

JS:ayb

FINAL CHANGE ORDER

0201 Banyan Elementary School

SUMMARY OF CHANGE ORDER NO.: 1

Project No.: A0809C Roof Replacment

								DOLLARS	DAYS	
TEM	ACTION REQ	ORIG.	Staff Auth.	ARG APPVD.	TYPE	CAUSE	REQ.	AUTH. REC.	REQ.	AUTH REC
1	С	С	04/20/2005	06/14/2005	sc	sc	31,105.00	31,105.00	0	
			Contractor pro- equipment to fr additional gut	urnish and in	stall					
2	С	С	04/20/2005	06/14/2005	UN	UC	6,032.00	6,032.00	0	
			Contractor pro- equipment to f expansion join unforeseen exi	urnish and in t due to an u	stall a ncovere	n		,		
3	С	С	04/20/2005	06/14/2005	OW	OR	(14,450.00)	(14,450.00)	0	
			Credit for FPL	insulation r	ebate p	rogram.				
4	A	С		06/14/2005	OT	RD	0.00	0.00	138	
			This is to ext date due to ra those allowed	in days above	and be	yond				
5	A	C		06/14/2005	ОТ	OR	0.00	0.00	29	:
			This is to ext date due to ad downspouts.			_				
6	A	С		06/14/2005	нс	UC	0.00	0.00	80	
			This is to ext date due to de for multiple h	mobilization		-				
						CHANGE	ORDER TOTAL:	22,687.00		1

FINAL CHANGE ORDER

SUMMARY OF CHANGE ORDER NO.: 1

Facility: 0201 Banyan Elementary School

Project No.: A0809C

Description: ROOF REPLACMENT Architect: ARCHITEKNICS, INC.

EFCO: WOLFBERG ALVAREZ & ASSOCIATES

Contractor: MURTON ROOFING CORP.

PRIME: JAMES C. MURTON

CC-- Criteria Change

CONTRACT STATUS

ORIGINAL CONTRACT PRICE\$	588,000.00
PREVIOUS EXTRAS\$ 0.00	
PREVIOUS CREDITS\$ 0.00	
PREVIOUS APPROVED NET CHANGE\$	0.00
PREVIOUS APPROVED CONTRACT PRICE\$	588,000.00
THIS CHANGE\$	22,687.00
TOTAL NET CHANGE\$	22,687.00
ADJUSTED CONTRACT PRICE AFTER THIS CHANGE\$	610,687.00
CONTRACT AWARD DATE	May 14, 2003
ORIGINAL CONTRACT COMPLETION DATE	April 09, 2004
PREVIOUS TIME EXTENSION	0
PREVIOUS ADJUSTED COMPLETION DATE	April 09, 2004
TIME EXTENSION THIS CHANGE	188
ADJUSTED COMPLETION DATE AFTER THIS CHANGE	October 14, 2004
PROJECTED COMPLETION DATE	N/A
SUBSTANTIAL COMPLETION DATE	October 14, 2004

CHANGE CAUSE SUMMARY:

CHANGE CACCE SOFFRAT:							
(Totals Including This Change Order.	Errors + 15%	Omissions th	reshold = $1-1/2\%$	ŧ			
TYPE	AMOUNT	8	DAYS				
ERRORS\$	0.00	0.00	0				
OMISSIONS\$	0.00	0.00	0				
OWNER REQUESTS\$	-14,450.00	-2.46	0				
unforeseen\$	6,032.00	1.03	0				
OTHER\$	0.00	0.00	188				
SCOPE CHANGE\$	31,105.00	5.29	0				
HURRICANE\$	0.00	0.00	0				
Totals\$	22,687,00	3.86	188				

Totals	\$	22,687.00	3.86	188
**************************************	**************************************	*********		**************************************
ORIGIN:	HCHurricane			CD Contractor Default
A A/E	OMP/A Omissio	on		CE Contractor Error
E Educational Fac. Plan.	OTOther			CR Contractor Request
P Project Manager	OWOwner Reque	est		FE Fastrack/Coord. Error
D DCPS Specialists/Depts.	SCScope Chang	je		FO Fastrack/Coord. Omission
C Contractor	UNUnforseen			ID Inspection Delay MD Manufacturer's Delay
S State DOE	CAUSE:	•		OO Owner Omission
M Maintenance Dept.	AEArchitect	ural Error		OD Owner Delay
U User (Principal/Admin.)	AOArchitect	ural Omission		OR Owner Request
I UBCI	EEEElectrica	l Engineering Error		RA Reinstate Alternate
AMAsbestos Mgmt.	EEOElectrica	l Engineering Omiss:		SC Scope Change
•	MEEMechanica	-Mechanical Engineering Error		SR State Requirement/Local/City
DSDesign Services (Group)	MEOMechanica	l Engineering Omiss:	ion	RD Rain Delay
CMConstruction Manager	SEEStructura	l Engineering Error		UC Unforseen Conditions UD Utility Co. Delay
ACTION:	SEOStructura	l Engineering Omiss:		CL Clerical Error
A Approve	CEECivil Engineering Error			UP Unit Price
C Confirm Staff/TRC Authorize	-	ineering Omission		UR Utility Requirement
C/AConfirm/Approce Authorize	DBRDesign-Builder Request			CMOConstruction Manager Omission
	-	-		CMEConstruction Manager Error
	DBEDesign-Bu	11der Error		CC Criteria Change