

ALTERNATE

2. CARLOS RIVERO PLUMBING & SEPTIC TANK
CONTRACTOR, INC.
10360 S.W. 34 STREET
MIAMI, FL 33165 ESTIMATE \$627,950
OWNER: JAVIER RIVERO, PRESIDENT

Total Low Unit Price: Items 1 through 9.

- Item 1 - Pump-out of grease trap, septic tank, lift station wetwell, storm drain or similar related receptacle or structure @ \$.135 per gallon.
 - Item 2 - Replace existing grease trap outlet tee @ \$0 each complete job.
 - Item 3 - Supply and install new grease trap outlet tee @ \$0 each complete job.
 - Item 4 - Patch all cracks and gaps in grease trap floors and walls, 0-10 lineal foot @ \$0 per lineal foot.
 - Item 5 - Patch all cracks and gaps in grease trap floors and walls, more than 10 lineal feet @ \$0 per lineal foot.
 - Item 6 - Replace tank floor with 4" nominal thickness concrete @ \$0 per square foot.
 - Item 7 - Remove debris from catch basin and drain lines (typical size is 4' x 4') @ \$125 each complete job.
 - Item 8 - Testing and reporting of effluent discharge for oil, grease, and pH @ \$130 each test with report.
 - Item 9 - Hourly rate for crew and equipment for standby or miscellaneous jetting not otherwise covered within the specifications @ \$100 per hour.
3. Authorize Procurement Management Services to purchase required services not to exceed the estimated amount of \$627,950.

OSP/lja

