Office of Superintendent of Schools Board Meeting of October 22, 2003

Business Operations
J.E. Surash, P.E., Chief Business Officer

SUBJECT:

CHANGE ORDER NO. 1 PROJECT NO. A0793A

DESIGN-BUILD - SAFETY-TO-LIFE PROJECT

GEORGE T. BAKER AVIATION

3275 NW 42 Avenue, Miami, Florida

COMMITTEE:

FACILITIES MANAGEMENT

This request for change in the construction contract includes four items for the School Board's confirmation and consideration. Attachment A presents a description of the items, the cause for each change, the effect upon the contract, and the action recommended to the Board. In order to prevent delay in the completion of the project, staff authorized the Contractor to proceed with item 1. These items are presented to the Board for confirmation and consideration as required by State Statute.

Change Items Synopsis: Additional cost and time to reconfigure footings; to reimburse the Design Builder for costs due to delays; and to extend the contract due to review delays.

This additional cost will <u>increase</u> the contract price by an amount of \$3,845 and <u>extend</u> the contract completion date by 38 days. These items have been recommended by the Project Architect and were confirmed/approved by the Technical Review Committee, subsequent to completion, on September 29, 2003. They were found to be necessary, fair, and equitable.

There is currently a fire watch on this school because of the fire alarm system. The fire watch will be removed upon completion of this project.

RECOMMENDED: That The School Board of Miami-Dade County, Florida, confirm

Change Order No. 1 on Project No. A0793A, Design-Build - Safety-to-Life Project, George T. Baker Aviation for an additional

cost of \$3,845 and approve a time extension of 38 days.

DB:avb

ATTACHMENT A

7801 BAKER, GEORGE T. AVIATION

SUMMARY OF CHANGE ORDER NO.: 1

Project No.: A0793A Design-Build - Safety-to-Life Project

	ACTION REQ	ORIG.	STAFF . AUTH.	ARG APPVD, TYPE		DOL	Lars	DAYS		
ITEM					TYPE CAUSE	CAUSE	REQ.	AUTH. REC.		AUTH. REC.
1	c	С	06/02/2003	09/09/2003	UN	UC	1,625.00	1,625.00	0	(
			Design Builder material and e footings at st of an existing underground pi	quipment to re air "A" due to extended foo	econfig the d	ure the iscovery				
2	A	С		09/09/2003	UN	UC	740.00	740.00	2	1
			This is to rei for additional delays caused existing exten footings for s	. job site cos by the discov ded footer at	ts due ery of	to an				
3	A	C		09/09/2003	UN	UC	1,480.00	1,480.00	4	
			This is to rei for additional delays caused underground pi stair "A".	. job site cos by the discov	ts due ery of	to existing				
4	A	С		09/09/2003	OT	CR	0.00	0.00	32	3
			This is to ext time due to ph delays.			-				
						CHANGE C	ORDER TOTAL:	3,845.00		3

SUMMARY OF CHANGE ORDER NO.: 1

Facility: 7801 BAKER, GEORGE T. AVIATION

Project No.: A0793A

Description: DESIGN-BUILD - SAFETY-TO-LIFE PROJECT

Architect: HARPER PARTNERS, INC. (DCP)
EFCO: RONALD E FRAZIER & ASSOC, PA

Contractor: G.C.C.M., INC. PRIME: AKRAM NIROOMAND

CONTRACT STATUS

ORIGINAL CONTRACT PRICE\$	749,500.00
PREVIOUS EXTRAS\$ 0.00	
PREVIOUS CREDITS\$ 0.00	
PREVIOUS APPROVED NET CHANGE\$	0.00
PREVIOUS APPROVED CONTRACT PRICE\$	749,500.00
THIS CHANGE\$	3,845.00
TOTAL NET CHANGE\$	3,845.00
ADJUSTED CONTRACT PRICE AFTER THIS CHANGE\$	753,345.00
CONTRACT AWARD DATE	October 23, 2002
ORIGINAL CONTRACT COMPLETION DATE	June 04, 2003
PREVIOUS TIME EXTENSION	0
PREVIOUS ADJUSTED COMPLETION DATE	June 04, 2003
TIME EXTENSION THIS CHANGE	38
ADJUSTED COMPLETION DATE AFTER THIS CHANGE	July 12, 2003
PROJECTED COMPLETION DATE	October 23, 2003
SUBSTANTIAL COMPLETION DATE	N/A

DODDIMITIM COMPETER.			41/			
CHANGE CAUSE SUMMARY:						
(Totals Including This Change Order.	Errors + 15 %	Omissions	threshold = $2-1/2%$			
TYPE	AMOUNT	*	DAYS			
ERRORS\$	0.00	0.00	0			
OMISSIONS\$	0.00	0.00	0			
OWNER REQUESTS\$	0.00	0.00	0			
unforeseen\$	3,845.00	0.51	6			
OTHER\$	0.00	0.00	32			
SCOPE CHANGE\$	0.00	0.00	0			
HURRICANE\$	0.00	0.00	0			
Totals\$	3,845.00	0.51	38			

*****	*********	******		
	TYPE: ERPA/E Error	DBODesign-Builder Omission DBDDesign-Builder Default		
ORIGIN:	HCHurricane Andrew	CD Contractor Default		
A A/E	OMP/A Omission	CE Contractor Error CR Contractor Request FE Fastrack/Coord. Error FO Fastrack/Coord. Omission ID Inspection Delay MD Manufacturer's Delay		
E Educational Fac. Plan.	OTOther			
P Project Manager	OWOwner Request			
D DCPS Specialists/Depts.	SCScope Change			
C Contractor	UNUnforseen			
S State DOE	CAUSE: AEArchitectural Error	OO Owner Omission		
M Maintenance Dept.	AOArchitectural Omission	OD Owner Delay OR Owner Request RA Reinstate Alternate SC Scope Change SR State Requirement/Local/City RD Rain Delay UC Unforseen Conditions		
U User (Principal/Admin.)	EEEElectrical Engineering Error			
I UBÇI	EECElectrical Engineering Omission			
AMAsbestos Mgmt.	MEEMechanical Engineering Error			
DSDesign Services (Group)	MEOMechanical Engineering Omission			
CMConstruction Manager	SEEStructural Engineering Error			
ACTION:	SEOStructural Engineering Omission	UD Utility Co. Delay CL Clerical Error		
A Approve	CEECivil Engineering Error	UP Unit Price UR Utility Requirement		
C Confirm Staff/TRC Authorize				
C/AConfirm/Approce Authorize		CMOConstruction Manager Omission CMEConstruction Manager Error		

CC-- Criteria Change