Business Operations
Ofelia San Pedro, Deputy Superintendent

SUBJECT:

FINAL CHANGE ORDER NO. 1

PROJECT NO. LV0069

HAZARD MITIGATION RETROFIT AMERICAN SENIOR HIGH SCHOOL

18350 NW 67 AVENUE, MIAMI, FLORIDA

COMMITTEE:

**FACILITIES MANAGEMENT** 

This request for change in the construction contract includes two items for the School Board's confirmation and consideration. Attachment A presents a description of the items, the cause for the change, the effect upon the contract, and the action recommended to the Board. In order to prevent delay in the completion of the project, staff authorized the Contractor to proceed with item 1. This item is presented to the Board for confirmation and consideration as required by State Statute.

Change Items Synopsis: Additional cost and time to modify the structural installation of the skylights.

This change will <u>increase</u> the contract price by \$12,034 and <u>extend</u> the contract completion date by 40 days. These items have been recommended by the Project Architect and were confirmed/approved by the Technical Review Committee, subsequent to completion, on October 19, 2004. They were found to be necessary, fair, and equitable.

Contract Closeout Status: There are no outstranding punchlist items, mandatories or provisos; and all required deliverables have been received.

RECOMMENDED: That The School Board of Miami-Dade County, Florida, confirm

Final Change Order No. 1 on Project No. LV0069, Hazard Mitigation Retrofit, American Senior High School for an additional cost of \$12,034 and approve a time extension of 40 days.

EF:ayb

FINAL CHANGE ORDER

ATTACHMENT A

7011 American Senior High SUMMARY OF CHANGE ORDER NO.: 1

Project No.: LV0069 Hazard Mitigation Retrofit

							****	DOLLARS	DAYS	
ITEM	ACTION REQ	ORIG.	STAFF AUTH.	ARG APPVD.	TYPE	CAUSE	REQ.	AUTH. REC.	REQ.	AUTH. REC.
1	c	c	06/30/2004	10/11/2004	UN	UC	14,339.71	12,034.00	0	0
			Contractor pro	,						
			equipment to m	odify the str	uctural					
			installation o	of the eleven a	new aky	lights				
			in order to ra	ise the exist:	ing cur	bs to				
			meet current o	odes. This wa	as nece	ssary				
			since the exis	ting structura	al stee	1				
			connecting ang	les were show	n on th	e record				
			drawings to be	longer and in	nstalle	d higher				
			than was actua	lly discovered	d upon					
			disassembly.							
2	A	c		10/11/2004	UN	UC	0.00	0.00	40	40
			This is to extend the contract completion							
			date due to the skylights installation							
			structural mod	lifications.						
						CHANGE OF	EDER TOTAL:	12,034.00		40

FINAL CHANGE ORDER

SUMMARY OF CHANGE ORDER NO.: 1

Facility: 7011 American Senior High

Project No.: LV0069

Description: HAZARD MITIGATION RETROFIT

Architect: LIVS ASSOCIATES

EFCO: BERMELLO, AJAMIL & PARTNERS

Contractor: Weiss & Woolrich Southern enterprises, prime: Jeffrey Weiss

## CONTRACT STATUS

ORIGINAL CONTRACT PRICE\$	337,989.00
PREVIOUS EXTRAS\$ 0.00	
PREVIOUS CREDITS\$ 0.00	
PREVIOUS APPROVED NET CHANGE\$	0.00
PREVIOUS APPROVED CONTRACT PRICE\$	337,989.00
THIS CHANGE\$	12,034.00
TOTAL NET CHANGE\$	12,034.00
ADJUSTED CONTRACT PRICE AFTER THIS CHANGE\$	350,023.00
CONTRACT AWARD DATE	January 14, 2004
ORIGINAL CONTRACT COMPLETION DATE	May 13, 2004
PREVIOUS TIME EXTENSION	0
PREVIOUS ADJUSTED COMPLETION DATE	May 13, 2004
TIME EXTENSION THIS CHANGE	40
ADJUSTED COMPLETION DATE AFTER THIS CHANGE	June 22, 2004
PROJECTED COMPLETION DATE	n/A
SUBSTANTIAL COMPLETION DATE	June 22, 2004

## CHANGE CAUSE SUMMARY:

(Totals Including This Change Order.	Errors + 15%	Omissions	threshold = $2-1/2$ %
TYPE	TIUOMA	<del>የ</del> ቴ	DAYS
ERRORS\$	0.00	0.00	0
omissions\$	0.00	0.00	0
OWNER REQUESTS\$	0.00	0.00	0
unforeseen\$	12,034.00	3.56	40
OTHER\$	0.00	0.00	0
SCOPE CHANGE\$	0.00	0.00	0
HURRICANE\$	0.00	0.00	0
Totals\$	12,034.00	3.56	40

*******	•	
LEGEND:	TYPE: ERPA/E Error	DBODesign-Builder Omission DBDDesign-Builder Default
ORIGIN:	HCHurricane Andrew	CD Contractor Default
A A/E	OMP/A Omission	CE Contractor Error
E Educational Fac. Pla	an. OTOther	CR Contractor Request
P Project Manager	OWOwner Request	FE Fastrack/Coord. Error
D DCPS Specialists/Dep	pts. SCScope Change	FO Fastrack/Coord. Omission
C Contractor	UNUnforseen	ID Inspection Delay MD Manufacturer's Delay
S State DOE M Maintenance Dept.	CAUSE: AEArchitectural Error	OO Owner Omission OD Owner Delay
U User (Principal/Adm	AOArchitectural Omission in.) EEEElectrical Engineering Error	OR Owner Request RA Reinstate Alternate
AMAsbestos Mgmt.	EEOElectrical Engineering Omission MEEMechanical Engineering Error	SR State Requirement/Local/City
DSDesign Services (Gr CMConstruction Manage	MEOMechanical Engineering Omission	UC Unforseen Conditions
ACTION:	SEOStructural Engineering Omission	UD Utility Co. Delay CL Clerical Error
A Approve C Confirm Staff/TRC A C/AConfirm/Approce A	CEOCivil Engineering Omission	UP Unit Price UR Utility Requirement CMOConstruction Manager Omission CMEConstruction Manager Error CC Criteria Change
		<del>-</del>