

MEMORANDUM

October 18, 2005

TO: The Honorable Chair and Members of The School Board of
Miami-Dade County, Florida

FROM: Rudolph F. Crew, Superintendent of Schools *RFC*

**SUBJECT: WITHDRAWAL OF AGENDA ITEM E-146, AWARD BID NO. 064-EE09 -
GREASE TRAP, SEPTIC TANK AND STORM DRAIN PUMP-OUT AND
REPAIR SERVICES**

A notice of protest of award has been received, and the vendor has 10 days within the statutory guidelines to file for an Administrative Hearing, pursuant to Florida Statute and Board Rule. It is requested that this agenda item be withdrawn at this time.

RFC:crl
M580
Attachment

cc: Superintendent's Cabinet
School Board Attorney
Mr. Joseph A. Gomez
Ms. Joanne Koski

Business Operations
Ofelia San Pedro, Deputy Superintendent

**SUBJECT: AWARD BID NO. 064-EE09 – GREASE TRAP, SEPTIC TANK
AND STORM DRAIN PUMP-OUT AND REPAIR SERVICES**

COMMITTEE: INNOVATION, EFFICIENCY & GOVERNMENTAL RELATIONS

The purpose of this bid, opened on August 9, 2005, is to establish a contract, with a primary and an alternate vendor, to furnish, at firm unit prices, all labor, supervision, materials, equipment and transportation necessary to perform pump-out service and repair grease traps, septic tanks and storm drains, at various Miami-Dade County Public Schools facilities, for Regulatory Compliance. This is a term bid which states that the Board may purchase quantities, as may be required, at the unit price bid, but is not obligated to purchase any guaranteed amount. Of 101 vendors sent bid forms or card notices of this advertised bid, 8 responded, with 5 bids meeting specifications, 1 bid not meeting specifications and 2 no bids.

Fund Source
0100 - General

M/WBE Eligibility
None

RECOMMENDED: That The School Board of Miami-Dade County, Florida, **AWARD** Bid No. 064-EE09 – GREASE TRAP, SEPTIC TANK AND STORM DRAIN PUMP-OUT AND REPAIR SERVICES, to establish a contract, with a primary and an alternate vendor, to furnish, at firm unit prices, all labor, supervision, materials, equipment and transportation necessary to perform pump-out service and repair grease traps, septic tanks and storm drains, at various Miami-Dade County Public Schools facilities, for Regulatory Compliance, during the term of the bid, effective October 19, 2005, through October 18, 2006, as follows:

PRIMARY

1. ENVIRONMENTAL PERFORMANCE SYSTEMS, INC.
12650 N.W. SOUTH RIVER DRIVE
MEDLEY, FL 33178 ESTIMATE \$610,750
OWNER: GABRIEL A. POU, PRESIDENT

Total Low Unit Price: Items 1 through 9.

- Item 1 - Pump-out of grease trap, septic tank, lift station wetwell, storm drain or similar related receptacle or structure @ \$.13 per gallon.
- Item 2 - Replace existing grease trap outlet tee @ \$20 each complete job.
- Item 3 - Supply and install new grease trap outlet tee @ \$20 each complete job.
- Item 4 - Patch all cracks and gaps in grease trap floors and walls, 0-10 lineal feet @ \$1 per lineal foot.
- Item 5 - Patch all cracks and gaps in grease trap floors and walls, more than 10 lineal feet @ \$1 per lineal foot.
- Item 6 - Replace tank floor with 4" nominal thickness concrete @ \$2 per square foot.
- Item 7 - Remove debris from catch basin and drain lines (typical size is 4' x 4') @ \$100 each complete job.
- Item 8 - Testing and reporting of effluent discharge for oil, grease, and pH @ \$150 each test with report.
- Item 9 - Hourly rate for crew and equipment for standby or miscellaneous jetting not otherwise covered within the specifications @ \$140 per hour.

ALTERNATE

2. CARLOS RIVERO PLUMBING & SEPTIC TANK
CONTRACTOR, INC.
10360 S.W. 34 STREET
MIAMI, FL 33165 ESTIMATE \$627,950
OWNER: JAVIER RIVERO, PRESIDENT

Total Low Unit Price: Items 1 through 9.

- Item 1 - Pump-out of grease trap, septic tank, lift station wetwell, storm drain or similar related receptacle or structure @ \$.135 per gallon.
 - Item 2 - Replace existing grease trap outlet tee @ \$0 each complete job.
 - Item 3 - Supply and install new grease trap outlet tee @ \$0 each complete job.
 - Item 4 - Patch all cracks and gaps in grease trap floors and walls, 0-10 lineal foot @ \$0 per lineal foot.
 - Item 5 - Patch all cracks and gaps in grease trap floors and walls, more than 10 lineal feet @ \$0 per lineal foot.
 - Item 6 - Replace tank floor with 4" nominal thickness concrete @ \$0 per square foot.
 - Item 7 - Remove debris from catch basin and drain lines (typical size is 4' x 4') @ \$125 each complete job.
 - Item 8 - Testing and reporting of effluent discharge for oil, grease, and pH @ \$130 each test with report.
 - Item 9 - Hourly rate for crew and equipment for standby or miscellaneous jetting not otherwise covered within the specifications @ \$100 per hour.
3. Authorize Procurement Management Services to purchase required services not to exceed the estimated amount of \$627,950.

OSP/lja