Office of Superintendent of Schools Board Meeting of March 15, 2000

February 29,2000

Facilities Planning and Construction Paul J. Phillips, Chief Facilities Officer

SUBJECT: CHA

CHANGE ORDER NO. 1 PROJECT NO. A-0684

NEW SCHOOL

MLC "AA" M.A. MILAM ELEMENTARY SCHOOL

6020 W 16th Avenue, Hialeah, Florida

This request for change in the construction contract includes fifteen items for the School Board's confirmation. Attachment A presents a description of the items, the cause for each change, the effect upon the contract, and the action recommended to the Board. In order to prevent delay in the completion of the project, Staff authorized the Contractor to proceed with Items 1 through 15. These items are presented to the Board for confirmation as required by State Statute.

These changes will <u>increase</u> the contract price by \$79,815. These items have been recommended by the Project Architect and were confirmed by the Technical Review Committee, subsequent to completion, on February 1, 2000. They were found to be necessary, fair, and equitable.

The Project Architect will not receive additional fees for the item that resulted from an omission in the design phase of the project. This factor will become part of the evaluation of this firm for consideration of future work with this school system.

RECOMMENDED: That The School Board of Miami-Dade County, Florida, confirm

Change Order No. 1 on Project No. A-0684, New School, MLC "AA" M.A. Milam Elementary School for an extra of \$79,815.

MGP:ayb

## ATTACHMENT A

6401 MLC "AA" M.A. MILAM ELEMENTARY
SUMMARY OF CHANGE ORDER NO.: 1
Project No.: A-0684 New School

							DOLLARS			<del></del>	
ITEM	ACTION REQ	ORIG	STAFF . Auth.	ARG APPVD.	TYPE	CAUSE	REQ	•	AUTH. REC.	REQ.	AUTH REC
1	С	D	06/29/1999	01/27/2000	ОМ	AO	1,174.00	)	1,174.00	0	REC
			Design Builder material and eq install fluores the kitchen coo the specified i	uipment to f cent light f lers/freezer	urnish ixtures s, in l	and inside ieu of					
2	С	С	06/29/1999	01/27/2000	OT	UR	1,541.00	)	1,541.00	0	(
			This reimburses deposits for wa the City of Hia Department.	ter meters,	as requ	ired by					
3	С	С	06/29/1999	01/27/2000	OT	CIR	1,384.88		1,385.00	0	o
			This reimburses cost of electri substantial com	cal power sul	osequent	t to					
4	C	С	06/29/1999	01/27/2000	OT	SR	5,870.00		5,870.00	0	c
			This reimburses cost of an addi required by Mia Works.	tional traffi	ic study	, as					
5	c	С	06/29/1999	01/27/2000	OT	SR	11,309.00		11,309.00	0	0
			Design Builder parent drop-off be relocated by	area that wa	s requi	red to					
6	С	P	06/29/1999	01/27/2000	OW	OR	( 5,875.00)	(	5,875.00)	0	0
			Design Builder p furnishing and t flagpole, and t multi-purpose ro	installing th	ne speci	fied					
7	С	Ð	06/29/1999	01/27/2000	sc	sc	10,087.00		10,087.00	0	o
			Design Builder p material and eq	-	-	•					

## 6401 MLC "AA" M.A. MILAM ELEMENTARY SUMMARY OF CHANGE ORDER NO.: 1 Project No.: A-0684 New School

	ACTION		STAFF	ARG			_	DLLARS	DAYS	
ITEM	REQ	ORIG.	AUTH.	APPVD.	TYPE	CAUSE	REQ.	AUTH. REC.	REQ.	AUTH REC
			install an addi connected to Mi services.							
8	С	บ	06/29/1999	01/27/2000	sc	sc	815.00	403.00	0	
		:	Design Builder material and eq install an addi in the Band Roo	ruipment to f tional obser	urnish a	and				
9	c	P	06/29/1999	01/27/2000	sc	sc	624.00	624.00	o	(
		:	Design Builder material and eq install pigment on mechanical a	pipment to fed in lieu o	urnish a f clear	and sealer				
10	С	D	06/29/1999	01/27/2000	sc	sc	5,189.00	5,189.00	0	C
		:	Design Builder material and eq install panic h doors in lieu o in order to mee criteria. This doors and frame	uipment to f ardware on t f the specif t MDCPS curre also include	urnish a he locke ied lock ent desi	er room esets, gn				
11	С	D	06/29/1999	01/27/2000	sc	sc	267.00	267.00	0	c
		1	Design Builder ; material and eq equipment modif. MDCPS current d	uipment for l ications, in	kitchen order t	•				
12	С	Ð	06/29/1999	01/27/2000	sc	sc	23,308.00	21,784.00	0	0
		r i	Design Builder praterial and equinstall addition connected to Miles telecommunication	uipment to fu nal 2" diamen lam Elementan	urnish a ter cond ry for d	nd uits				

## ATTACHMENT A

6401 MLC "AA" M.A. MILAM ELEMENTARY SUMMARY OF CHANGE ORDER NO.: 1 Project No.: A-0684 New School

							DC	LLARS	DAYS	
ITEM	ACTION REQ	ORIG.	STAFF AUTH.	ARG APPVD.	TYPE	CAUSE	REQ.	AUTH. REC.	REQ.	AUTH. REC.
13	С	D	06/29/1999	01/27/2000	SC	sc	6,277.00	6,277.00	0	0
			Design Builder material and eq install additio meet MDCPS curr	quipment to f nal hardware	urnish in ord	and er to				
. 14	с		06/29/1999 This reimburses additional secu vandalism after occupancy.	rity costs d	Builder ue to re	epeated	2,972.00	2,972.00	0	o
15	С	:	O6/29/1999  Design Builder : material and eq install an unde system lateral City of Hialeah exist where the included street backfill, patch traffic control	uipment to furground sanit to connect to system. All City had sho cutting, exc ing, permitti	tary set the external control of the external control	and wer kisting did not This	16,808.00	16,808.00	0	0

CHANGE ORDER TOTAL: 79,815.00

SUMMARY OF CHANGE ORDER NO.: 1

Facility: 6401 MLC "AA" M.A. MILAM ELEMENTARY

Project No.: A-0684
Description: New School

Architect: Harper Partners, Inc. (DCP)

Contractor: Betancourt Castellon Associates, Inc. PRIME: Albert Castellon

CONTRACT STATUS

	\$	4,508,201.00
PREVIOUS EXTRAS		-,,
PREVIOUS CREDITS	\$ 0.00	
PREVIOUS APPROVED NET CH	ANGE\$	0.00
PREVIOUS APPROVED CONTRA	CT PRICE\$	
THIS CHANGE	\$	79,815.00
	(GE\$	79,815.00
	AFTER THIS CHANGE\$	4,588,016.00
CONTRACT AWARD DATE		May 13, 1998
ORIGINAL CONTRACT COMPLE	TION DATE	August 18, 1999
	EXTENSION	
PREVIOUS ADJUSTED COMPLE	TION DATE	August 18, 1999
	THIS CHANGE	0
	AFTER THIS CHANGE	August 18, 1999
PROJECTED COMPLETION DAT		N/A
ACCEPTANCE DATE		July 23, 1999

## CHANGE CAUSE SUMMARY:

(Totals Including This Change Order)

TYPE	AMOUNT	%	DAYS
ERRORS\$	0.00	0.00	0
OMISSIONS\$	1,174.00	0.02	0
OWNER REQUESTS\$	-5,875.00	-0.13	0
Unforseen\$	19,780.00	0.43	0
OTHER\$	20,105.00	0.44	0
SCOPE CHANGE\$	44,631.00	0.99	0
HURRICANE\$	0.00	0.00	o
Totals\$	79,815.00	1.77	0

	**************************************	************				
DEGRAD: T.	ERPA/E Error	DBODesign-Builder Omission				
ORIGIN:	HCHurricane Andrew	DBDDesign-Builder Default				
	· ·=··	CD Contractor Default				
A A/E	OMP/A Omission	CE Contractor Error				
E Educational Fac. Plan.	OTOther	CR Contracto Request				
P Project Manager	OWOwner Request	FE Fastrack/Coord. Error FO Fastrack/Coord. Omission				
D DCPS Specialists/Depts.	SCScope Change					
C Contractor	UNUnforseen	ID Inspection Delay				
	AUSE:	MD Manufacturer's Delay				
3 State DOE	AEArchitectural Error	OO Owner Omission				
M Maintenance Dept.		OD Owner Delay				
U User (Principal/Admin.)	AOArchitectural Omission	OR Owner Request				
I UBCI	EEEElectrical Engineering Error	RA Reinstate Alternate SC Scope Change SR State Requirement/Local/City				
AMAsbestos Mgmt.	EEOElectrical Engineering Omission					
<u></u>	MEOMechanical Engineering Error					
DSDesign Services (Group)	MEOMechanical Engineering Omission	RD Rain Delay				
CMConstruction Manager		UC Unforseen Conditions				
ACTION:	SEEStructural Engineering Error	UD Utility Co. Delay				
7 3	SEOStructural Engineering Omission	CL Clerical Error				
A Approve	CEECivil Engineering Error	UP Unit Price				
C Confirm Staff/TRC Authorize	CEOCivil Engineering Omission	UR Utility Requirement				
C/AConfirm/Approce Authorize	DBRDesign-Builder Request	CMOConstruction Manager Omission				
	DBEDesign-Builder Error	CMEConstruction Manager Error				