Facilities Planning and Construction
Suzanne A. Marshall, Chief Facilities Officer (Construction)

SUBJECT: FINAL CHANGE ORDER NO. 1

PROJECT NO. A0595 NEW GYMNASIUM

MIAMI DOUGLAS MACARTHUR NORTH 13835 NW 97 Avenue, Hialeah, Florida

This request for change in the construction contract includes six items for the School Board's confirmation and consideration. Attachment A presents a description of the items, the cause for each change, the effect upon the contract, and the action recommended to the Board. In order to prevent delay in the completion of the project, Staff authorized the Contractor to proceed with items 1 through 6. These items are presented to the Board for confirmation and consideration as required by State Statute.

These changes will decrease the contract price by \$1,599,541 and extend the REVISED contract completion date by 177 days. These items have been recommended by the Project Architect and were confirmed/approved by the Technical Review Committee, subsequent to completion, on June 29, 2001. They were found to be necessary, fair, and equitable.

RECOMMENDED: That The School Board of Miami-Dade County, Florida, confirm/approve Final Change Order No. 1 on Project No. A0595,

New Gymnasium, Miami Douglas MacArthur North for a credit of

\$1,599,541 and a time extension of 177 days.

**REVISE** 

EG:ayb

REVISED D-31

# FINAL CHANGE ORDER

7254

MIAMI DOUGLAS MACARTHUR NORTH

SUMMARY OF CHANGE ORDER NO.: 1

Project No.: A0595

New Gymnasium

			· · · · · · · · · · · · · · · · · · ·					DOLLARS	DAYS	
ITEM	ACTION REQ	ORIG	STAFF . AUTH.	ARG APPVD.	TYPE	CAUSE	REQ.	AUTH. REC.	REQ.	AUTH. REC.
1	C/A	С	02/22/2001	05/29/2001	OT	SR	46,528.00	23,497.00	93	92
			This reimburses							
			additional on-s	ite costs du	e to de	lays				
			caused by the s			_				
			the South Flori	da Water Man	agement					
			District.							
2	С	С	03/05/2001	05/29/2001	UN	uc	42,052.00	38,786.00	0	0
			Contractor prov	ided labor,	materia	l and				
			equipment to re	move and rep	lace ad	ditional				
			unsuitable soil	, as require	d by the	e				
			Geotechnical co	nsultant.						
3	C/A	С	03/05/2001	05/29/2001	UN	uc	58,931.00	19,767.00	131	78
			This reimburses	the Contrac	tor for					
			additional on-s	ite costs du	e to de:	lays				
			caused by the r			_				
			additional unsu	itable soil.						
4	С	С	03/05/2001	05/29/2001	บพ	υc	13,058.00	13,058.00	0	o
			Contractor prov	ided labour						
			equipment to ad							
			and regrade the			Сещиск				
			subsequent to t			nd				
			flooding in Oct		1411. 4					
				,						
5	C/A	С	03/05/2001	05/29/2001	UN	UC	1,716.00	1,716.00 1,716.00 7	7	7
			This reimburses	the Contract	tor for					
			additional on-s	ite costs du	e to de	lays				
			caused by exces	sive rain and	d flood:	ing in				
			October, 2000.							
6	С	P	05/08/2001	05/29/2001	บพ	UC	(1,696,365.00)	(1,696,365.00)	o	0
			Contractor prov	ided a credi	t for no	ot	REVI	SED		
			completing the	remaining so	cope of	the				
			contract. The							
			directed to sto	p all work a	nd demoi	bilized				
			from the site d		_	_				
			clearance to pr	oceed with th	ne work	from				

ATTACHMENT A

### FINAL CHANGE ORDER

7254 MIAMI DOUGLAS MACARTHUR NORTH SUMMARY OF CHANGE ORDER NO.: 1

Project No.: A0595 New Gymnasium

								DOLLARS	DAYS	
	ACTION		STAFF	ARG			REQ.	AUTH.		AUTH.
ITEM	REQ	ORIG.	AUTH.	APPVD.	TYPE	CAUSE		REC.	REQ.	REC.

the Miami-Dade County Department of Environmental Regulation and the South Florida Water Management District. It has been determined to be in the Board's best interest to close this contract at this time.

CHANGE ORDER TOTAL:

-1,599,541.00 REVISED

177

#### FINAL CHANGE ORDER

SUMMARY OF CHANGE ORDER NO.:

7254 MIAMI DOUGLAS MACARTHUR NORTH Facility:

Project No.: A0595

Description: New Gymnasium

Architect: Architects International, Inc.

Contractor: J.V. Construction Corporation PRIME:

# CONTRACT STATUS

ORIGINAL CONTRACT PRICE\$	1,998,000.00
PREVIOUS EXTRAS\$ 0.00	
PREVIOUS CREDITS\$ 0.00	
PREVIOUS APPROVED NET CHANGE\$	0.00
PREVIOUS APPROVED CONTRACT PRICE\$	1,998,000.00
THIS CHANGE\$	-,,011.00
TOTAL NET CHANGE\$	-1,599,541.00 REVISED
ADJUSTED CONTRACT PRICE AFTER THIS CHANGE\$	398,459.00
CONTRACT AWARD DATE	May 17, 2000
ORIGINAL CONTRACT COMPLETION DATE	June 16, 2001
PREVIOUS TIME EXTENSION	0
PREVIOUS ADJUSTED COMPLETION DATE	June 16, 2001
TIME EXTENSION THIS CHANGE	177
ADJUSTED COMPLETION DATE AFTER THIS CHANGE	December 10, 2001
PROJECTED COMPLETION DATE	N/A

### CHANGE CAUSE SUMMARY:

SUBSTANTIAL COMPLETION DATE.....

## (Totals Including This Change Order)

TYPE	THUOMA	ક	DAYS	
ERRORS\$	0.00	0.00	0	Ĭ
OMISSIONS\$	0.00	0.00	0	
OWNER REQUESTS\$	0.00	0.00	0	
UNFORESEEN\$	~1,623,038.00	-81.23	85	REVISED
OTHER\$	23,497.00	1.17	92	
SCOPE CHANGE\$	0.00	0.00	0	ŀ
HURRICANE\$	0.00	0.00	0	
Totals\$	-1,599,541.00	-80.05	177	

LEGEND: ER--PA/E Error DBD--Design-Builder Default ORIGIN: HC--Hurricane Andrew CD-- Contractor Default

A-- A/E

E-- Educational Fac. Plan.

P-- Project Manager

D-- DCPS Specialists/Depts.

C-- Contractor

S-- State DOE M-- Maintenance Dept.

AO --Architectural Omission

U-- User (Principal/Admin.)

I-- UBCI

AM--Asbestos Momt.

DS--Design Services (Group)

CM--Construction Manager

### ACTION:

A-- Approve

C-- Confirm Staff/TRC Authorize

C/A--Confirm/Approce Authorize

TYPE:

OM--P/A Omission

OT--Other OW--Owner Request

SC--Scope Change UN--Unforseen

CAUSE:

AE --Architectural Error

EEE--Electrical Engineering Error

EEO--Electrical Engineering Omission

MEO--Mechanical Engineering Error MEO--Mechanical Engineering Omission

SEE--Structural Engineering Error

SEO--Structural Engineering Omission

CEE--Civil Engineering Error CEO--Civil Engineering Omission

DBR--Design-Builder Request DBE--Design-Builder Error

DBO--Design-Builder Omission

CE-- Contractor Error CR-- Contracto Request

N/A

FE-- Fastrack/Coord. Error FO-- Fastrack/Coord. Omission

ID-- Inspection Delay MD-- Manufacturer's Delay

OO-- Owner Omission OD-- Owner Delay OR-- Owner Request RA-- Reinstate Alternate

SC-- Scope Change

SR-- State Requirement/Local/City

RD-- Rain Delay

UC-- Unforseen Conditions UD-- Utility Co. Delay CL-- Clerical Error UP-- Unit Price

UR-- Utility Requirement

CMO--Construction Manager Omission CME--Construction Manager Error