Office of Superintendent of Schools Board Meeting of May 15, 2002

May 9, 2002

Business Operations Joe Arriola, Chief Business Officer

SUBJECT:

FINAL CHANGE ORDER NO. 1

PROJECT NO. 0019-KS **ROOF REPLACEMENT**

MIAMI DOUGLAS MACARTHUR (SOUTH) - ALT/ED

11035 SW 84 Street, Miami, Florida

This request for change in the construction contract includes ten items for the School Board's confirmation and consideration. Attachment A presents a description of the items, the cause for each change, the effect upon the contract, and the action recommended to the Board. In order to prevent delay in the completion of the project, Staff authorized the Contractor to proceed with items 1 through 8. These items are presented to the Board for confirmation and consideration as required by State Statute.

Change Items Synopsis: A credit for FPL rebate; removal and replacement of malfunctioning exhaust fans; new corridor ceiling; additional roofing work due to unforeseen conditions; and time extensions for stopping work due to excessive noise and for rain delays.

These changes will increase the contract price by \$43,686 and extend the contract completion date by 31 days. These items have been recommended by the Project Architect, completed by the Contractor and confirmed/approved on April 23, 2002 by the Technical Review Committee. They were found to be necessary, fair, and equitable.

RECOMMENDED: That The School Board of Miami-Dade County, Florida, confirm/approve Final Change Order No. 1 on Project No. 0019-KS, Roof Replacement, Miami Douglas MacArthur (South) - Alt/Ed REVISE for additional cost of \$43,686 and a time extension of 31 days.

JR:ayb

FINAL CHANGE ORDER

ATTACHMENT A

7631 MIAMI DOUGLAS MACARTHUR (SOUTH) - ALT/ED REVISED

SUMMARY OF CHANGE ORDER NO.: 1

Project No.: 0019-KS Roof Replacement

		<u>-</u>		·					DOL	LARS	DAYS	
ITEM	ACTION REQ	ORIG	STAFF . AUTH.	ARG APPVD.	TYPE	CAUSE		REQ.		AUTH. REC.	REQ.	AUTH. REC.
1	С	P	04/07/2001	04/18/2002	OW	OR	(11,178.00)	(11,178.00)	0	0
			Contractor pro		t for th	ne FPL						
2	6/2	_	07/04/0004									
2	C/A	P	07/24/2001	04/18/2002	OW	OR		3,000.00		3,000.00	2	1.
			Contractor pro	=								
			equipment to r malfunctioning									
			exhaust fans o									
			gymnasium buil									
3	С	υ	06/27/2001	04/18/2002	sc	sc		8,675.00		8,675.00	5	o
			Contractor pro	vided labor, m	naterial	. and						
			equipment to f	urnish and ins	stall ne	ew .						
			suspended ceil	ing with light	t fixtur	es in						
			existing corri	dors in class	room bui	ldings						
			#1 and #2.									
4	С	Þ	02/05/2001	04/18/2002	UN	UC		7,087.00		7,087.00	3	0
			Contractor pro-	vided labor, m	material	. and						
			equipment to d	emolish and re	emove th	e						
			existing deter									
			roof structure shop.	adjacent to f	the auto	repair						
5	С	С	02/05/2001	04/18/2002	UN	UC		8,779.00		7,118.00	4	0
			Contractor pro-	vided labor, m	naterial	and						
			equipment to re	epair and repl	lace exi	sting						
			deteriorated g	ypsum roof dec	ek.							
6	С	С	06/06/2001	04/18/2002	UN	UC.		6,923.00		6,923.00	6	0
			Contractor pro-	vided labor, r	material	. and						
			equipment to f	urnish and ins	stall							
			additional room	-		•						
			"M-1", and "N"		correct	the						
			existing negat	тля вторе.								

FINAL CHANGE ORDER

ATTACHMENT A

7631

MIAMI DOUGLAS MACARTHUR (SOUTH) - ALT/ED REVISED

SUMMARY OF CHANGE ORDER NO.: 1

Project No.: 0019-KS

Roof Replacement

			 ,				DO	LLARS	DAYS	
	ACTION		STAFF	ARG			REQ.	AUTH.		AUTH.
ITEM	REQ	ORIG.	AUTH.	APPVD.	TYPE	CAUSE		REC.	REQ.	REC.
7	C	P	06/13/2001	04/18/2002	UN	UC	18,325.00	18,325.00	10	0
		•	Contractor pro	vided labor,	material	Land				
			equipment to f	urnish and in	stall a					
			Miami-Dade Cou	nty product-a	pproved	special				
			roofing adhesi	ve to fasten	the root	Ē				
			system, since	the existing	lightwe:	ight				
			concrete did n	_	-					
			strength for t	he specified	mechanio	cal				
			fastening syst	em.						
8	С	С	08/20/2001	04/18/2002	UN	UC	3,736.00	3,736.00	4	0
			Contractor pro	ovided labor,	materia.	l and				
			equipment to w	rap existing	exterio:	r HVAC				
			system ductwor							
			membrane to pr	event water i	nfiltra	tion				
			through the ro	of at the gym	nasium					
			building.							
9	A	ប		04/18/2002	OT	CR	0.00	0.00	2	2
			This is to ext	tend the contr	act com	pletion				
			time due to th							
			to stop work h							
			noise level,		t disru	pt				
			school operati	ions.						
10	A	С		04/18/2002	UN	RD	0.00	0.00	28	28
			This is to ext	bond the sert-		nletion				
			time due to ra							
			those allowed	=		-				
										
						CHANGE C	ORDER TOTAL:	43,686.00		31

CME--Construction Manager Error

CC-- Criteria Change

```
FINAL CHANGE ORDER
```

SUMMARY OF CHANGE ORDER NO.: 1

Facility: 7631 MIAMI DOUGLAS MACARTHUR (SOUTH) - ALT/ED REVISED

Project No.: 0019-KS

Description: ROOF REPLACEMENT

Architect: KUNDE, SPRECHER & ASSOCIATES

EFCO:

SPILLIS CANDELA & PARTNERS INC.

Contractor: WEISS & WOOLRICH SOUTHERN ENTERPRISES, PRIME: JEFFREY WEISS

CONTRACT STATUS

ORIGINAL CONTRACT PRICE\$	795,000.00
REDUCTION OF USED CONTINGENCY\$ 0.00	•
CONTRACT PRICE AFTER CONTINGENCY\$	795,000.00
PREVIOUS EXTRAS\$ 0.00	12070000
PREVIOUS CREDITS\$ 0.00	
PREVIOUS APPROVED NET CHANGE\$	0.00
PREVIOUS APPROVED CONTRACT PRICE\$	
THIS CHANGE\$	124,000
TOTAL NET CHANGE\$	43,686.00
ADJUSTED CONTRACT PRICE AFTER THIS CHANGE\$,000.00
CONTRACT AWARD DATE	0,500.00
ORIGINAL CONTRACT COMPLETION DATE	, 2000
PREVIOUS TIME EXTENSION	
DESITORS AD HIGHER CONTRACTOR DATE.	0
PREVIOUS ADJUSTED COMPLETION DATE	August 07, 2001
TIME EXTENSION THIS CHANGE	31
ADJUSTED COMPLETION DATE AFTER THIS CHANGE	September 07, 2001
PROJECTED COMPLETION DATE	N/A
SUBSTANTIAL COMPLETION DATE	September 07, 2001

CHANGE CAUSE SUMMARY:

(Totals Including This Change Order)

TYPE	AMOUNT	9e	DAYS
ERRORS\$	0.00	0.00	0
OMISSIONS\$	0.00	0.00	0
OWNER REQUESTS\$	-8,178.00	-1.02	1
UNFORESEEN\$	43,189.00	5.43	28
OTHER\$	0.00	0.00	2
SCOPE CHANGE\$	8,675.00	1.09	0
HURRICANE\$	0.00	0.00	ō
Totals\$	43,686.00	5.49	31

	******************************	***********************			
LEGEND:	TYPE: ERPA/E Error	DBODesign-Builder Omission			
ORIGIN:	HCHurricane Andrew	DBDDesign-Builder Default			
A A/E	OMP/A Omission	CD Contractor Default			
E Educational Fac. Plan.	OTOther	CE Contractor Error CR Contractor Request			
P Project Manager	OWOwner Request	FE Fastrack/Coord. Error			
D DCPS Specialists/Depts.	SCScope Change	FO Fastrack/Coord. Omission			
C Contractor	UNUnforseen	ID Inspection Delay			
S State DOE	CAUSE:	MD Manufacturer's Delay			
•	AEArchitectural Error	00 Owner Omission			
M Maintenance Dept.	AOArchitectural Omission	OD Owner Delay			
U User (Principal/Admin.)		OR Owner Request			
I UBCI	EEEElectrical Engineering Error	RA Reinstate Alternate			
AMAsbestos Mqmt.	EEOElectrical Engineering Omission	SC Scope Change			
DSDesign Services (Group)	MEOMechanical Engineering Error	SR State Requirement/Local/Ci			
	MEOMechanical Engineering Omission	RD Rain Delay			
CMConstruction Manager	SEEStructural Engineering Error	UC Unforseen Conditions			
ACTION:		UD Utility Co. Delay			
A Approve	SEOStructural Engineering Omission	CL Clerical Error			
C Confirm Staff/TRC Authorize	CEECivil Engineering Error	UP Unit Price			
	CFOCiveil Englisher of the c	UR Utility Requirement CMOConstruction Manager Omission			
C/AConfirm/Approce Authorize	DBRDesign-Builder Request				
		MRCanadama-63 M 7			