Office of Superintendent of Schools Board Meeting of October 22, 2003

Business Operations
J.E. Surash, P.E., Chief Business Officer

SUBJECT:

CHANGE ORDER NO. 2 PROJECT NO. A0713

**DESIGN-BUILD** 

S/S "LL1" @ HORACE MANN MIDDLE SITE

8950 NW 2 Avenue, El Portal, Florida

COMMITTEE: FACILITIES MANAGEMENT

This request for change in the construction contract includes two items for the School Board's confirmation. Attachment A presents a description of the items, the cause for the change, the effect upon the contract, and the action recommended to the Board. In order to prevent delay in the completion of the project, staff authorized the Surety to proceed with items 1 and 2. These items are presented to the Board for confirmation as required by State Statute.

Change Items Synopsis: Additional cost to extend sidewalk and add largerthan-specified sewer pumps.

These additional costs will <u>increase</u> the contract price by an amount of \$23,609. These items have been recommended by the Design Criteria Specialist and were confirmed by the Technical Review Committee, subsequent to completion, on September 29, 2003. It was found to be necessary, fair, and equitable.

The Design Criteria Specialist will not receive additional fees for the item that resulted from an omission in the design phase of the project. This factor will become part of the evaluation of this firm for consideration of future work with this school system. The District will pursue recovery of costs from the Project Architect as called for in the contract.

This project was phased and the addition was completed in May, 2003, and occupied in August, 2003.

This project is the subject of a claim by the Surety against the Board and a counterclaim by MDCPS, and is not yet in litigation.

RECOMMENDED: That The School Board of Miami-Dade County, Florida, confirm Change Order No. 2 on Project No. A0713, Design-Build, S/S "LL1" @ Horace Mann Middle Site for an additional cost of \$23,609.

MK:ayb

## ATTACHMENT A

6651 S/S "LL1" @ HORACE MANN MIDDLE SITE

SUMMARY OF CHANGE ORDER NO.: 2

Project No.: A0713 Design-Build

						DC	DOLLARS			
ITEM	ACTION REQ	ORIG.	Staff Auth.	ARG APPVD.	TYPE	CAUSE	REQ.	AUTH. REC.	REQ.	AUTH. REC.
1	С	ט	04/24/2003	09/09/2003	OM	AO	3,818.29	1,208.00	0	0
			Surety provide equipment to e meet the exist	xtend the sou	th side	walk to				
2	c	c	04/24/2003	09/09/2003	OT.	SR	25,382.31	22,401.00	0	0
			Surety provide equipment to f larger-than-sp station pumps, electrical ser	furnish and in ecified sanit piping and s	stall ary sew ssociat	er lift ed				
						CHANGE O	RDER TOTAL:	23,609.00		0

SUMMARY OF CHANGE ORDER NO.: 2

Facility: 6651 S/S "LL1" @ HORACE MANN MIDDLE SITE

Project No.: A0713

Description: DESIGN-BUILD

Architect: MATEU, CARRENO, RIZO & PARTNERS (DCP)

EFCO:

RONALD E FRAZIER & ASSOC, PA

Contractor: SURETY FOR JV CONSTRUCTION

## CONTRACT STATUS

ORIGINAL CONTRACT PRICE\$	4,045,620.00
PREVIOUS EXTRAS \$ 18,898.00	
PREVIOUS CREDITS\$ 0.00	
PREVIOUS APPROVED NET CHANGE\$	18,888.00
PREVIOUS APPROVED CONTRACT PRICE\$	
THIS CHANGE\$	
TOTAL NET CHANGE\$	
ADJUSTED CONTRACT PRICE AFTER THIS CHANGE\$	4,088,117.00
CONTRACT AWARD DATE	July 14, 1999
ORIGINAL CONTRACT COMPLETION DATE	December 29, 2000
PREVIOUS TIME EXTENSION	0
PREVIOUS ADJUSTED COMPLETION DATE	December 29, 2000
TIME EXTENSION THIS CHANGE	0
ADJUSTED COMPLETION DATE AFTER THIS CHANGE	December 29, 2000
PROJECTED COMPLETION DATE	October 23, 2003
SUBSTANTIAL COMPLETION DATE	N/A

PRIME:

## CHANGE CAUSE SUMMARY:

(Totals Including This Change Order.	Errors + 15 %	Omissions	threshold = $2-1/2%$
TYPE	AMOUNT	8	DAYS
ERRORS\$	0.00	0.00	0
omissions\$	1,208.00	0.02	0
OWNER REQUESTS\$	0.00	0.00	0
Unforeseen\$	18,888.00	0.46	0
OTHER\$	22,401.00	0.55	0
SCOPE CHANGE\$	0.00	0.00	0
HURRICANE\$	0.00	0.00	0
Totals\$	42,497.00	1.05	0

	42,497,00	U5 U
***********  LEGEND:  ORIGIN:  A A/E  E Educational Fac. Plan.  P Project Manager  D DCPS Specialists/Depts.  C Contractor  S State DOE  M Maintenance Dept.  U User (Principal/Admin.)  I UBCI  AMAsbestos Mgmt.	**************************************	***********************  DBODesign-Builder Omission  DBDDesign-Builder Default  CD Contractor Default  CE Contractor Request  FE Fastrack/Coord. Error  FO Fastrack/Coord. Omission  ID Inspection Delay  MD Manufacturer's Delay  CO Owner Omission  OD Owner Delay  OR Owner Request  RA Reinstate Alternate  SC Scope Change  SR State Requirement/Local/City
U User (Principal/Admin.) I UBCI	AEArchitectural Error  AOArchitectural Omission  EEEElectrical Engineering Error	OD Owner Delay OR Owner Request RA Reinstate Alternate SC Scope Change