Office of Superintendent of Schools Board Meeting of January 12, 2000

December 10, 1999

Facilities Planning and Construction Paul J. Phillips, Chief Facilities Officer

SUBJECT: FINAL CHANGE ORDER NO. 8

PROJECT NO. A-0317-22 ACOUSTICAL CEILINGS

MIAMI EDISON MIDDLE SCHOOL 6101 NW 2 Avenue, Miami, Florida

This request for change in the construction contract includes one item for the School Board's confirmation. Attachment A presents a description of the item, the cause for the change, the effect upon the contract, and the action recommended to the Board. This item is presented to the Board for confirmation as required by State Statute.

This change will increase the contract price by \$25,000. This item has been recommended by the Project Architect and was confirmed by the Technical Review Committee, subsequent to completion, on December 6, 1999. It was found to be necessary, fair, and equitable.

RECOMMENDED: That The School Board of Miami-Dade County, Florida, confirm

Final Change Order No. 8 on Project No. A-0317-22, Acoustical Ceilings, Miami Edison Middle School for an extra of \$25,000.

EL:ayb

FINAL CHANGE ORDER

ATTACHMENT A

6481 MIAMI EDISON MIDDLE

SUMMARY OF CHANGE ORDER NO.: 8

Project No.: A-0317-22 Acoustical Ceilings

ITEM	ACTION REQ	ORIG.	STAFF AUTH.	ARG APPVD.			DOLLARS		DAYS	
					TYPE	CAUSE	REQ.	AUTH. REC.	REQ.	AUTH. REC.
1	С	С	11/17/1999	11/29/1999	OT	CR	39,000.00	25,000.00	0	0
		o c	his final nego utstanding cla ontractor for nd numerous re	ims reimburse additional o	es the n-site	costs				

CHANGE ORDER TOTAL:

25,000.00

## FINAL CHANGE ORDER

SUMMARY OF CHANGE ORDER NO.: 8

6481 MIAMI EDISON MIDDLE

Project No.: A-0317-22

Description: Acoustical Ceilings

Architect: R.J. Heisenbottle & Associated Contractor: B & B Interior Systems PRIME: Jeffrey A. Burley

	mm. perried W. RailfeA
CONTRACT STATUS	•
ORIGINAL CONTRACT PRICE	\$ 123,320.00
PREVIOUS EXTRAS\$ 26,544.	00
PREVIOUS CREDITS\$ 55.695.	00
PREVIOUS APPROVED NET CHANGE	-29,151.00
PREVIOUS APPROVED CONTRACT PRICE	\$ 94,169.00
THIS CHANGE	-\$ 25,000.00
TOTAL NET CHANGE	
ADJUSTED CONTRACT PRICE AFTER THIS CHANGE	\$ 119.169.00
CONTRACT AWARD DATE	January 25, 1995
ORIGINAL CONTRACT COMPLETION DATE	
PREVIOUS TIME EXTENSION	639
PREVIOUS ADJUSTED COMPLETION DATE	· · · · December 15, 1997
TIME EXTENSION THIS CHANGE	0
ADJUSTED COMPLETION DATE AFTER THIS CHANGE.	December 15, 1997
PROJECTED COMPLETION DATE	
ACCEPTANCE DATE	
	December 15, 1997

## CHANGE CAUSE SUMMARY:

## (Totals Including This Change Order)

TYPE	AMOUNT	*	DAYS
ERRORS\$	590.00	0.47	0
OMMISSIONS\$	4,327.00	3.50	0
OWNER REQUESTS\$	-48,800.00	-39.57	0
UNFORSEEN\$	140.00	0.11	0
OTHER\$	39,592.00	32.10	639
SCOPE CHANGE\$	0.00	0.00	0
HURRICANE\$	0.00	. 0.00	0
Totals\$	-4,151.00	-3.36	639

LEGEND:	<pre>FYPE:     ERPA/E Error</pre>	DBODesign-Builder Ommission		
ORIGIN:	HCHurricane Andrew	DBDDesign-Builder Default		
A A/E	OMP/A Ommission	CD Contractor Default CE Contractor Error CR Contracto Request FE Fastrack/Coord. Error		
E Educational Fac. Plan.	OTOther			
P Project Manager	OWOwner Request			
D DCPS Specialists/Depts.	SCScope Change	FO Fastrack/Coord. Ommission		
C Contractor	UNUnforseen	ID Inspection Delay MD Manufacturer's Delay		
S State DOE	CAUSE:			
	AEArchitectural Error	OO Owner Ommission		
M Maintenance Dept.	AOArchitectural Ommission	OD Owner Delay		
U User (Principal/Admin.)		OR Owner Request		
I UBCI	EEEElectrical Engineering Error	RA Reinstate Alternate SC Scope Change SR State Requirement/Local/City RD Rain Delay		
AMAsbestos Mgmt.	EEOElectrical Engineering Ommission			
DSDesign Services (Group)	MEOMechanical Engineering Error			
CMConstruction Manager	MEOMechanical Engineering Ommission			
di constituction manager	SEEStructural Engineering Error	UC Unforseen Conditions		
ACTION:		UD Utility Co. Delay		
A Approve	SEOStructural Engineering Ommission	CL Clerical Error UP Unit Price		
C Confirm Staff/TRC Authorize	CEECivil Engineering Error			
C/AConfirm/Approce Authorize	CEOCivil Engineering Ommission	UR Utility Requirement		
-, GOUNTIMY APPLOCE AUTHORIZE	DBRDesign-Builder Request	CMOConstruction Manager Ommission		
•	DBEDesign-Builder Error	CMEConstruction Manager Error		